PRINTED: 12/11/2015 FORM APPROVED

Division of Health Service Regulation

(X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 B. WING FCL032133 11/10/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 2801 BEECHWOOD DR **SPRING VALLEY BEECHWOOD** DURHAM, NC 27707 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 000 Initial Comments C 000 Report by Paul Dixon DHSR Construction Section conducted a Biennial Survey on November 10, 2015 from 2:05 PM to 3:15 PM at the above referenced facility. DHSR records indicate the home was first licensed on November 14, 2013 as a Family Care Home for three (3) ambulatory Residents (able to evacuate and respond without any physical or verbal assistance during a fire or other emergency). Based on this information we are requiring the home to maintain compliance with the following: the 2005 Rules 10A NCAC 13G for Family Care Homes, the 2012 North Carolina State Residential Building Code - Section R101.2. At the time of our visit, we cited deficiencies that require an acceptable plan of correction. They are as follows: C 174 Building Equipment Maintained Safe, Operating C 174 SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE **EQUIPMENT** (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1. Observations during the survey showed that the kitchen range hood fan was not working. Have a qualified individual investigate and repair or replace the fan. Provide the DHSR Construction section with copies of all invoices, work orders, receipts, photographs and any other

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

PRINTED: 12/11/2015 FORM APPROVED

If continuation sheet 2 of 3

Division of Health Service Regulation

DIVISION	of Health Service Re	eguiation	r					
STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA			(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY			
AND PLAN OF CORRECTION IDEN		IDENTIFICATION NUMBER:	A. BUILDING: 01		COMPLETED			
		FCL032133	B. WING		11/1	0/2015		
			<u>l</u>			0/2010		
NAME OF	PROVIDER OR SUPPLIER	STREET AD	DRESS, CITY, S	STATE, ZIP CODE				
SPRING VALLEY BEECHWOOD 2801 BEECHWOOD DR								
DURHAM, NC 27707								
(X4) ID	SUMMARY STA	TEMENT OF DEFICIENCIES	ID	PROVIDER'S PLAN OF CORRECTION	NC	(X5)		
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		PREFIX (EACH CORRECTIVE ACTION SHOUL TAG CROSS-REFERENCED TO THE APPRODEFICIENCY)			COMPLETE DATE		
TAG					TRIALE	DATE		
C 174	Continued From page 1		C 174					
	supporting documentation concerning this repair.							
		uring the survey showed that build-up of lint behind the						
	clothes dryer, and there was some trash behind the clothes washer. Clean out behind the							
	washer and dryer. Provide the DHSR							
	Construction section with copies of all invoices,							
	work orders, receipts, photographs and any other							
		ntation concerning this repair.						
	3. Observations during the survey showed that							
	3. Observations during the survey showed that the Fire Extinguishers in the facility have an							
	inspection tag dated June 2014. Take the fire							
	extinguishers to an authorized fire equipment							
	company and have them inspected and							
	re-tagged. Provide the DHSR Construction							
	section with copies of all invoices, work orders,							
	receipts, photographs and any other supporting							
	documentation con	cerning this repair.						
	4. Observations during the our vey abouted that							
	4. Observations during the survey showed that							
	the HVAC return air grill above the hallway entrance had a heavy build-up of dust on the grill.							
	Have the grill cleaned and the filter replace if							
		e the DHSR Construction						
		of all invoices, work orders,						
		hs and any other supporting						
	documentation con							
		iring the survey showed that						
	the smoke detector in the hallway was missing							
	the battery. Install a new battery in the smoke							
		he DHSR Construction section						
	with copies of all invoices, work orders, receipts, photographs and any other supporting							
	documentation con	cerning this repair.						
	6. Observations du	uring the survey showed that						
		ver in the hall bathroom was						

6899

Division of Health Service Regulation STATE FORM

PRINTED: 12/11/2015 FORM APPROVED

Division of Health Service Regulation

AND DIAN OF CORRECTION INTERPRETATION NUMBER:	(2) MULTIPLE CONSTRUCTION . BUILDING: 01	(X3) DATE SURVEY COMPLETED					
FCL032133 B. V	. WING	11/10/2015					
NAME OF PROVIDER OR SUPPLIER STREET ADDRES	DRESS, CITY, STATE, ZIP CODE						
SPRING VALLEY BEECHWOOD 2801 BEECHWOOD DR DURHAM, NC 27707							
(X4) ID SUMMARY STATEMENT OF DEFICIENCIES	ID PROVIDER'S PLAN OF CORRECTION SHOULD CROSS-REFERENCED TO THE APPROPRIES OF THE AP	D BE COMPLETE					
C 174 Continued From page 2 clogged with dust and lint. Have the cover cleaned to ensure an unobstructed air flow. Provide the DHSR Construction section with copies of all invoices, work orders, receipts, photographs and any other supporting documentation concerning this repair. 7. Observations during the survey showed that the light fixture in the front bedroom is missing a bulb. Install a working light bulb in the fixture. Provide the DHSR Construction section with copies of all invoices, work orders, receipts, photographs and any other supporting documentation concerning this repair. 8. Observations during the survey showed that the exterior hood and screen for the clothes dryer is completely clogged with lint. Have the hood and screen cleaned out. Provide the DHSR Construction section with copies of all invoices, work orders, receipts, photographs and any other supporting documentation concerning this repair.	C 174						

Division of Health Service Regulation STATE FORM